

**Appendix 2.** Site photos.

**Photo 1.** View of Existing Denil-type Fish Ladder with Stoplogs and Interior Baffles Removed, Looking Downstream.



**Photo 2.** View of the deep pond looking north from the outlet to the scour channel.



**Photo 3.** View of Agricultural Road Crossing 2 from the Yolo Bypass east levee.





**Photo 4.** View of upstream, northern face of Agricultural Road Crossing 2 (looking south) showing excessive vegetation build-up clogging an undersized culvert.



**Photo 5.** View of downstream face of Agricultural Road Crossing 2 (facing south) showing vegetation build-up.





**Photo 6.** View of Agricultural Road Crossing 3 looking towards the Yolo Bypass east levee.



**Photo 7.** View upstream of Agricultural Road Crossing 3, showing vegetation growth concealing an undersized culvert looking north on road crossing.

